C 8050

UTC Standard Inspection Report Intrastate Gas Distribution R C - State Statutes and Rules Records Review and Field Inspections

PRINT Form (select "save and keep working" first)

PHMSA Advisory Bulletins

Inspector and Operator Information

Inspection ID Insp. No. Inspector - Lead Inspector - Assist

8050 8050 Rukke, Scott

Operator Unit Records Location - City & State

Cascade Natural Gas Kennewick Kennewick WA

Inspection Start Date Inspection Exit Interview Date Engineer Submit Date

10-07-2020 11-11-2020

Inspection Summary This inspection was a standard unit inspection for the Kennewick District.

Instructions and Ratings Definitions

INISTRUCTIONS	INSPECTION RESULTS

S - Satisfactory

U - Unsatisfactory Unsatisfactory Responses Unsatisfactory List

0

Area Of Concern Responses Area of Concern List

0

N/A - Not Applicable (does not apply in this inspection)

Not Applicable Responses

Not Applicable List

3 4,5,6,

List

N/C - Not Checked/Evaluated (was not inspected during Not Checked / Evaluated Not Checked / Evaluated

this inspection) Responses

1 12,

Records, Procedures and Reports

Question #1.

Has the operator provided accurate maps (or updates) of pipelines operating over 250PSIG to specifications developed by the commission and sufficient to meet the needs of first responders?

Statutory Reference1. Result1. NotesRCW 81.88.080SatisfactoryCNG OPS 10
section 16.

Question #2.

Does the operator have a procedure for leaks caused by excavation damage near buildings and determine whether the procedures adequately address the possibility of multiple leaks and underground migration of gas into nearby buildings.

Statutory Reference 2. Result 2. Notes

WAC 480-93-180(1)

Satisfactory

CNG CP 750 - Outside
Leak Investigation.

1 of 4 11/18/2020, 1:27 PM

^{**}If an item is marked U, N/A or N/C, an explanation must be included in this report.

Question #3.

Does the operator have a procedure for dealing with leaks caused by excavation damage near buildings? Do the procedures adequately address the possibility of multiple leaks and underground migration of gas into nearby buildings?

Statutory Reference

3. Result

3. Notes

WAC 480-93-180(1)

Satisfactory

CNG CP 750 - Outside Leak Investigation.

Question #4

Does the operator have a quality assurance program in place for monitoring the locating and marking of facilities? Do operators conduct regular field audits of the performance of locators/contractors and take action when necessary? (CGA Best Practices. Recommended, not required)

Reference:

4. Results Not Applicable Q4. Within Scope of this Inspection:

4. Notes

Operator Internal Performance

Measures; PHMSA State

Program Guidelines No such event occurred, or condition

Cascade Natural Gas does

existed.

not use contractor

locators.

Question #5.

Does operator include performance measures in facility locating services contracts with corresponding and meaningful incentives and penalties?

Statutory Reference

480-93-007

Statutory Reference

Reference:

5. Result

Q5. Within Scope of

5. Notes

WAC

WAC 480-93-013 **PHMSA State Program** Guidelines

Not **Applicable** this Inspection: No such event occurred, or condition existed.

Cascade Natural Gas does not use contract locators.

Question #6.

Do locate contractors address performance problems for persons performing locating services through mechanisms such as retraining, process change, or changes in staffing levels?

Statutory Reference

Statutory Reference 6. Result

Q6. Within Scope of this Inspection:

6. Notes

WAC 480-93-007

WAC 480-93-013

Not Applicable

No such event occurred, or condition existed.

Cascade Natural Gas does not use contract locators.

Question #7.

Does the operator periodically review the Operator Qualification plan criteria and methods used to qualify personnel to perform locates?

Statutory Reference

Statutory Reference

7. Result

7. Notes

WAC 480-93-007

WAC 480-93-013

Satisfactory

EWN and CNG OQ task (Task Locating

Pipelines)

CNG uses form 293 and form 23001 is used for documenting missed locates.

Question #8.

Are operator locating and excavation procedures in compliance with RCW 19.122?

Statutory Reference RCW 19.122

Statutory Reference WAC 480-93-250

8. Result Satisfactory 8. Notes **CNG CP 836**

Question #9.

2 of 4 11/18/2020, 1:27 PM Are locates made within the required timelines specified within RCW 19.122 (2 full business days)? Examine record sample.

Statutory Reference

Statutory Reference

9. Result

9. Notes

RCW 19.122

WAC 480-93-250

Satisfactory

A sampling of locate requests were reviewed and were compliant.

Question #10.

Are locating and excavating personnel properly qualified in accordance with the operator's Operator Qualification plan and with federal and state requirements?

Statutory Reference

Statutory Reference

10. Result

10. Notes

WAC 480-93-007

WAC 480-93-013

Satisfactory

OQ records were reviewed for personnel performing covered

tasks. .

Question #11.

Is the operator appropriately addressing discovered mapping errors, including those that have resulted in excavation damage?

Reference:

11. Result

11. Notes

PHMSA State Program Guidelines

Operator Internal Performance

Measures

Satisfactory

CNG CP 836 (Updating GIS). CNG Form 286 has a

mapping error section that triggers a follow up for

necessary mapping corrections.

Question #12.

Are mapping corrections timely and according to written procedures?

Reference:

12. Result Not Checked/Evaluated 12. Notes

No necessary mapping errors corrections were apparent during

document review

PHMSA State Program

Guidelines

Operator Internal Performance

Measures

Question #13

Are Annual Reports filed with the commission no later than March 15 for the proceeding year?

Statutory Reference WAC 480-93-200(10) 13. Result

13. Notes

Satisfactory

No issues.

Question #14.

Did the operator submit a copy of DOT Drug and Alcohol Testing MIS Data Collection Form to the commission when required?

Statutory Reference

14. Result

14. **Notes**

WAC 480-93-200(13)

Satisfactory

No

issues.

Question #15

Are shorted conditions leak surveyed within 90 days of discovery and twice annually/not to exceed 7.5 months?

Statutory Reference

15. Result

15. Notes

WAC 480-93-110(5)(d)

Satisfactory

Reviewed during the electronic

records review.

Comments - Records, Procedures & Reports

Comments - Records Review - Any rating other than Satisfactory, requires comments. Ensure you annotate the question number for each comment.

3 of 4 11/18/2020, 1:27 PM Notes were placeed in the appropriate questions.

Field Inspection Observations

Question #16

Welding procedures located on site where welding is performed?

Statutory Reference 16. Results 16. Note

WAC 480-93-080(1)(e) Satisfactory Welding procedures are available electronically on laptops carried

by field personnel.

Question #17

Is the operator using testing equipment necessary to record and document essential variables during welder and procedure testing/qualifications?

Statutory Reference 17. Results 17. Notes

WAC 480-93-080(1)(c) Satisfactory Welding qualification records indicate that

essential variables are being measured.

Comments - Field Observations

Comments - Field Observations - Any rating other than Satisfactory, requires comments. Ensure you annotate the question number for each comment.

N/A

4 of 4 11/18/2020, 1:27 PM